

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.

Lease No. D.P. 97867-1

Unit 8

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 4 is located 2510 ft. from N line and 2510 ft. from E line of sec. 21  
NE 1/4 Sec. 21 (1/4 Sec. and Sec. No.) 10N (Twp.) 3E (Range) 107W (Meridian)  
Wildcat (Field) Sandoval (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6779 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was drilled to total depth of 1375 feet and no commercial oil or gas was found and it was decided to abandon same. Telephonic permission was requested and granted on August 12 to place plug in bottom of hole and 100 foot plug between 754 and 874 and 10 foot plug was placed at surface with surface pipe left in hole and cemented with plug.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company \_\_\_\_\_

Address 439 Camino del Monte Sol,

Santa Fe, New Mexico

By J. I. Harvey,

Operator

Title By Jack B. [Signature]

