


FORM NO. 100-1
1-57

(SUBMIT IN TRIPPLICATE)

Indian Agency NAVAJOUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYAllottee TRIBAL
Lease No. I-149-IND. 7973

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(CHECK ONE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

AUGUST 16, 1960

Well No. 1-X is located 1980 ft. from S line and 660 ft. from E line of sec. 22
38 22 18N 4W NEPM
 (4 Sec. and Sec. No.) (Top) (Range) (Meridian)
UNDESIGNATED SANDOVAL NEW MEXICO
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6340 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

HOLE WAS FILLED WITH MUD AND 15 SACKS OF CEMENT SPOTTED ON BOTTOM FROM 870 TO TOTAL DEPTH OF 993 FEET. SPOTTED 10 SACKS OF CEMENT IN TOP OF WELL TO A DEPTH OF 70 FEET. IRON HOLE MARKER WAS ERECTED. OLD CASING WAS LEFT IN THE WELL.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company REYNOLDS MINING CORPORATIONAddress 609 MELROSE BLDG., HOUSTON, TEXASBy C. J. ESKRIDGE, JR.,
Title CHIEF PETROLEUM ENGINEER