


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 043266

Unit Anderson-Board (Fed)



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 18, 1961

Well No. 1 is located 1650 ft. from N line and 000 ft. from E line of sec. 10

Section 10 (1/4 Sec. and Sec. No.) 18 N (Twp.) 2W (Range) R. 1 E (Meridian)
Unknown (Field) San Juan County (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6215 ft. 00.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded: May 20, 1961
Completed: June 21, 1961
Remarks:
total depth 1435' in sandy shale
No show oil
No show water in any appreciable amount.
Will install well monument with well name & location.
Will clean and level location.

CEMENTING WITH 100 LB. CEMENT
Interval to: Cement w/ 10 lbs cement
1400'
Cement w/ 10 lbs cement
800'
Cement w/ 10 lbs cement
300'
Cement w/ 10 lbs cement
in casing to surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W.W. Holmes

Address Box 567
Amarillo, Texas

By _____

Title Office Manager