


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **081163-D**
Lease No. _____
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 3, 1956

Goso & Hiett
Well No. **1** is located **330** ft. from **N** line and **330** ft. from **E** line of sec. **12**
12 Sec. **12** **18N** **31**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Sandoval **N.M.**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6630** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

March 26, 1956

Well plugged and abandoned as follows:

TD 1647

25 Sx Cement 1550 to 1450

25 Sx Cement 910 to 850

20 Sx cement 290 to 245

5 Sx Cement intop of 10" surface casing which was left in hole. Put up marker in last plug.

Plugging program approved by Mr. Long

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **F.H. Goso & Carey Hiett**
Address **P.O. Box 11321**
Fort Worth, Texas.
By **F.H. Goso**
Title **Partner**