



1 VanDyke
1 Pan American (SUBMIT IN TRIPPLICATE)
1 Horace Melay
1 File

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Santa Fe
Lease No. 11-021213
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 7, 1963

Well No. 1 is located 940 ft. from NE line and 1565 ft. from E line of sec. 21
SW/4 SE/4 Sec 21 19N 1W 106E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Albuquerque Sandoval New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground level above sea level is 6739 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged in the following manner:

1. Filled open hole 1480-1150 w/21 sacks cement.
2. Put 4 sz plug in top of 7" pipe.
3. Installed dry hole marker and abandoned well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Reese and Van Dyke

Address P.O. Box 3117

Albuquerque, New Mexico

By Original signed by T. A. Dugan

Title Consulting Engineer