

DRILL STEM TEST

NO.	DATE	FROM	TO	OPEN HOLE	TOOL SET #	CHOKES TOP	CHOKES BOTTOM	WATER CUSHION	TIME TESTED
1	12-10-53	5187	5202	Open Hole	5187	1"	1"	None	1 Hour

Entrada, 2 packers, Nothing to surface, Recovered 1580' free oil, 90' mud cut oil, no water, SFP - 0%, BHFP 130 - 540%, 20 minutes SIP 2020%, HH 2460' in & out.

DEVIATION SURVEY

DEPTH	DEGREES OFF VERTICAL	DEPTH	DEGREES OFF VERTICAL	DEPTH	DEGREES OFF VERTICAL
260	1	2525	1/4	4420	3/4
443	1/2	2730	3/4	4890	1
925	3/4	3508	1		

CORE RECORD

NO.	FROM	TO	REC	DESCRIPTION
1	5160	5175	15'	5160 - 5165 Red Sand 5165 - 5166 Light gray lime w/shale stringers 5166 - 5169 Red & Gray Shale. 5169 - 5174 Pink shaley sand.
2	5175	5202	23'	20' Anhydrite 3' Fine grain to medium grain sand with good stain & fluorescence.

OIL CONSERVATION COMMISSION	
STATE DISTRICT OFFICE	
New Copies Received	
DISTRIBUTION	
COPIES	TO
	Operator
	State Engineer
	Production Office
	State Land Office
	U. S. D. S.
	Transporter
	File



REPORT OF THE
COMMISSIONER OF THE
LAND OFFICE

REPORT OF THE COMMISSIONER OF THE LAND OFFICE, STATE OF NEW MEXICO, FOR THE YEAR 1917.

REPORT OF THE COMMISSIONER OF THE LAND OFFICE, STATE OF NEW MEXICO, FOR THE YEAR 1917.

REPORT OF THE
COMMISSIONER OF THE
LAND OFFICE

REPORT OF THE COMMISSIONER OF THE LAND OFFICE, STATE OF NEW MEXICO, FOR THE YEAR 1917.

REPORT OF THE
COMMISSIONER OF THE
LAND OFFICE

REPORT OF THE COMMISSIONER OF THE LAND OFFICE, STATE OF NEW MEXICO, FOR THE YEAR 1917.

REPORT OF THE COMMISSIONER OF THE LAND OFFICE, STATE OF NEW MEXICO, FOR THE YEAR 1917.

OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Received <u>5</u>		
DISTRIBUTION		
	NO. FURNISHED	
Operator	<u>1</u>	
Santa Fe	<u>1</u>	
Proration Office		
State Land Office		
U. S. G. S.	<u>2</u>	
Transporter		
File	<u>1</u>	✓