

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe**  
Lease No. **87 079109-8**  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 23, 1960

Well No. **1-4** is located **640** ft. from **[N]** line and **1000** ft. from **[E]** line of sec. **13**

**NE/4 SE/4 Sec. 13** **T 21N** **R 8 W** **100W**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

**Wilcox** **Sandoval Co.** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is **6624** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate cementing points, and all other important proposed work)

The well was plugged as follows:

3 sacks at surface  
30 sacks from 630 to 730 feet  
30 sacks from 1250 to 1450 feet  
30 sacks from 3100 to 3200 feet  
30 sacks from 4075 to 4175 feet  
45 sacks from 5000 to 5150 feet



The location cleaned and graded and leveled, and permanent marker erected.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **DAVIS OIL COMPANY**  
Address **1020 MIDLAND AVENUE BLDG.**  
**DENVER 1, COLORADO**

By **E. L. Karna, Jr.**  
Title **Production Manager**