

Santa Fe

Land Office


ST 097119-1

Lease No.

Unit

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 1

19 58

Well No. 1 Govt. located 660 ft. from {N} line and 660 ft. from {E} line of sec. 10

SE/4 SW/4 Sec. 10
(1/4 Sec. and Sec. No.)

T 11 N - R 6 E
(Twp.) (Range)

107N
(Meridian)

Wilcox
(Field)

Sandoval County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6930 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

For following cement plugs in compliance with verbal instructions from District Engineer of the U.S.G.S.:

3 marks at top of surface pipe

30 " 950' to 1100'
35 " 1450' to 1550'
35 " 4450' to 4550'
35 " 5400' to 5500'
35 " 5700' to 5801'

Pits filled, location cleaned and graded, water erected, and is now ready for your inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVIS OIL COMPANY

Address 1023 Midland Savings Bldg.

Denver 2, Colorado

By

Paul Heringer

Title

Expl. Engr., Southern Co.