



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 27-080097
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | <u>Recompletion</u> |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 20, 1958

Sandoval 22-7
Well No. 1-23 is located 1900 ft. from SE line and 660 ft. from E line of Sec 23NE/4 SE/4 23 22N 7W Range
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat (Gallup) Sandoval New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the water grad ~~surface~~ above sea level is 6801 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ID 5975'. PDB 4920'. MI & HU workover unit 1-2-58. Removed pumping unit and pulled rods, tubing and pump equipment. Dred out CI return at 4760'. Perforated w/6 SPV fr 4754-64. Set pbr at 4750' and frac GP w/10,000 gals crude and 5,000# oil. ID 3100'-1700'. Avg 1200'. Max 2900'. IR 12 RPM. Perforated w/6 SPV fr 4678-84. Set BP at 4720' and frac GP w/10,000 gals crude and 10,000# oil. ID 1700'-1500'. Avg 2000'. Max 2100'. IR 33 RPM. Cleaned out oil and pushed BP to 4920'. Set 4793.58' of 2-3/8" OD J-55 4.74 lb/ft tubing at 4802.58' w/cement nipple at 4766.02' and anchor at 4642.36'. Ran rods and installed pump. Started pumping load oil at 4 pm 1-18-58. Released unit 8 pm 1-18-58.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____
Address ROCKWELL PRODUCTION CORPORATION
600 - 6th Ave Building
Albuquerque, New Mexico
By RAY PHILLIPS
Ray Phillips
Title Asst Mgr, Prod Opr