## (SUBMIT IN TRIPLICATE)

## \*

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

ncian Agency	
Jicarilla Aj	peche
Mottee	
.ease No	· · · · · · · · · · · · · · · · · · ·
	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Coment plug from 250 up into shoe.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company	CASWELL SILVER	
Address	323 Simms Building	
	Albuquerque, New Mexico	By Carrell Selve
		TitleOperator