

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Jicarilla
Allottee _____
Lease No. **49(B)**

		X

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 5, 1961, 19____

Well No. **1-B** is located **990** ft. from **N** line and **990** ft. from **E** line of sec. _____
NE/4 Sec. 1 **22N-5W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated **Sandoval** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6785** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Covered perforations (5820-40) with cement. Pulled casing to approximately 1900'. Placed cement plug in top of 5' stub. Placed cement plug at surface with 5' marker.

cc: **Frank Yockey**
Box 2055, Farmington, N.M.
Humble O & R Co.
P.O. Box 3082, Durango, Colo.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Arizona Explorations, Inc.**
Address **417 Meadows Bldg.**
Dallas 6, Texas

By **Rex Ortey**
Title **V.P.**