

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **SP 078274**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent report on drillstem test X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 18, 1958


Well No. **1 Fulton** located **660** ft. from **N** line and **660** ft. from **E** line of sec. **31**
SE 1/4 Sec. 31 **23 North 7 West** (Meridian)
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox **Sandoval** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6634** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud June 18, 1958
 Set 100 ft. 9-5/8 casing with 100 cks. Pumped returns to surface.
 Total 30 minutes with 130 p.s.i. Drillstem test July 25, 1958.
 5898-5931. Tool open 1-1/2 hours. Recovered 1560 ft. slightly
 brackish water, 300 ft. mud. FP 200 # SIP (30 Min.) 1900 W.M.R. 3230 #.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **E. B. LaRue, Jr.**
 Address **First National Bank Bldg.**
P. O. Box 209
Athens, Texas
 By **E. B. LaRue, Jr.**
 Title **Operator**