

(SUBMIT IN TRIPLICATE)

Indian Agency JicarillaContract No. 54Allottee Tract No. 104Lease No. 1041

APPROVED

MAR 12 1956	
33	(Orig. Sgd.) J. W. LON
ACTING DISTRICT ENGINEER	

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Open Hole Drill	
	Stem Test Nos. 1 and 2	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 6, 1956

Well No. D-1 is located 790 ft. from N line and 790 ft. from W line of sec. 33SE/4 NW/4 of 33  
(1/4 Sec. and Sec. No.)T-23-N  
(Twp.)R-3-W  
(Range)NMPM  
(Meridian)Wildcat  
(Field)Sandoval County  
(County or Subdivision)New Mexico  
(State or Territory)The elevation of the derrick floor above sea level is 7329 ft. ground level

## DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

- DST No. 1 - 2916 to 2942 feet. One-inch top and bottom chokes. Recovered 1440 feet drilling mud with no odor or fluorescence. Packer failure. No test. Test conducted January 4, 1956.
- DST No. 2 - 2917 to 2941 feet. One-inch top and bottom chokes. Length of test 4 hours. No water cushion. Very weak blow immediately and died in five minutes. No pressure recorded. Misrun. Test conducted January 5, 1956.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Reynolds Mining Corporation  
Oil and Gas Division  
Address 152 1/2 East 9th Street  
Post Office Box 1328  
Durango, Colorado

By C. J. Eskridge, Jr.  
Title District Petroleum Engineer



**CONCLUSIONS**