

Sec. 19

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo Tribal

Contr. #142

Allottee

Lease No. Navajo #1UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 14,

U. S. GEOLOGICAL SURVEY  
FARMINGTON NEW MEXICOWell No. 1 is located 990 ft. from N line and 990 ft. from W line of sec. 19

Rt. 19

(14 Sec. and Sec. No.)

23 N 2W

(Twp.)

(Range)

100 N, N, P, N.

(Meridian)

Undesignated P.O.

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 7407 ft. Est.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 3229' of 5 1/2" casing w/ 3229' w/145 sacks of cement. Plug down 2:00 A.M.  
10-11-58. WOC 24 hrs. Run temperature survey, top of cement @ 2930'  
Tested w/1000' 30 min., held O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NAVALIA PETROLEUM COMPANYAddress Box 2406Albuquerque, New MexicoBy [Signature]Title District Superintendent