

1		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R368.4.
Approval expires 12-31-60.

Land Office Santa Fe, N. M.

Lease No. 079150

Unit Duff Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO
1959

September 14,

Well No. 1 is located 990 ft. from ~~11~~ line and 990 ft. from ~~11~~ line of sec. 19
 NW/4 Sec 19 23N 1W NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
 Undesignated Pictured Cliffs Sandoval New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7346 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 98 fts 3053' of 4 1/2" csg to 3065' w/50 sks 8% gel + 1/2 floccle sk + 50 neat.
 Good circulation. 7:45 A. M. 9-12-59.

Test 4 1/2" csg w/1200# 15 min. Hold OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Magnolia Petroleum Company

Address Box 2406

Santa Fe, New Mexico

By [Signature]

Title District Superintendent