

F. Loc. 995/S; 905/W Elev. 6442 GR Spd. _____ Comp. _____ ID _____ PB _____

Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ Grav. _____ Ist Del. _____ s. _____

TOPS		NITD	Well Log	TEST DATA						
Kirtland		C-103	Plat	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104	Electric Log							
Pictured Cliffs			C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout		Aband. ¹¹⁻¹⁻⁶⁷ Loc.								
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										

P
o
o
l

Co. Sand 27 T. 18N R. 3W U.M. Oper. Tenneco Oil Co. Lse. Torreon Core Test No. 8