

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Contract 15

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cinco Diablos

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

Ballard P. C.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19-T23N-R3W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, AT, OR, etc.)

7191 (Gr)

12. COUNTY OR PARISH

13. STATE

Sandoval

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud well ~~July~~ ^{June} 25, 1968~~June~~ ^{July} 26, 1968

Total depth 125'

Ran 3 jts. 8 5/8", 20.0#, J-55 casing (108.71')

Set at 118.71' with 100 sacks cement with
3% calcium chloride circulated to surface.Tested casing with 500 psi for
30 minutes. Test O.K.

RECEIVED

JUL 25 1968

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

P. E. TITLE

Petroleum Engineer

Consultant

DATE 7-25-68

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side