

November 18, 1968

T. J. Krentschman and Arwood Stowe
Well No. "C" Mike # 1
Section 13 17N 3W Sandoval County, New Mexico
1000' from the South line
1980' from the East line
Ground Elev. 6422'

Rotary
C & M Drilling Company, Contractor

Surface Plug
Plug 100-200

100 to 110	Sandstone	
110	120	Coal and Sandstone
120	140	Siltstone and Bentonite
140	180	Sandstone, Siltstone
		(Light tan oil show, oil fluorescence) + 6282
180	210	Bentonite & Shale
210	260	Sandstone & Shale
260	300	Sandstone, TOP POINT LOOKOUT
		(tan oil stain, oil fluorescence) + 6182
		(oil on pits)
300	360	Sandstone (no oil show)
360	460	Sandstone, Shale & Siltstone
460	480	Sandstone
480	520	Sandstone & siltstone
520	540	Sandstone
540	600	Sandstone & Siltstone
600	900	Siltstone & sandstone
900	920	Sandstone
920	1000	Sandstone & Siltstone
1000	1020	Sandstone & Siltstone (thin coal streak)
1020	1040	Sandstone & Siltstone
1040	1050	Siltstone
1050	1070	Sandstone & Siltstone
1070	1090	Sandstone & Siltstone (coal streak)
1090	1140	Sandstone & siltstone TOP GALLUP SANDSTONE + 5332
1140	1170	Sandstone, Siltstone & Shale
1170	1200	Sandstone, Siltstone & Shale
		(Dead oil stain, spotty light oil stain + 5252)
		and fluorescence.)
1200	1210	Sandstone, Siltstone & Shale
1210	1230	Sandstone, Siltstone & Shale
1230	1250	Sandstone, Siltstone & Shale
		<u>TOTAL DEPTH</u>

Plug 1040 TO 1250

RECEIVED

APR 28 1969

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

Instructions were
Plug from 1090' to
TD but had fillup
to 1040'

No Electric Log run
Plugged well - Cement
10' plug in top of marker
Plug 100' to 200'
Plug 1040 to 1250'