



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 20, 1985

Mr. Hap Post
Kirby Exploration Co. of Texas
P.O. Box 640
Cuba, NM 87013

Re: ✓ Media Unit #8 WIW N-14-19N-3W
Media Unit #1 WIW H-15-19N-3W
Federal Boling #5 WIW C-22-19N-3W

Dear Mr. Post:

Annual mechanical integrity tests on the referenced water injection wells indicate casing or packer leaks. In order to insure the protection of hydrocarbon bearing and fresh water zones, you are hereby directed to initiate remedial action within 60 days. Copies of the tests are enclosed for your reference.

Yours truly,

A handwritten signature in cursive script, reading "Carolyn J. Taplin".

Carolyn J. Taplin
Field Representative

CJT/dj

xc: ✓ Prentiss Childs
Well File
UIC File
Operator File