

Distribution:

Orig+4 (BLM); 1-Crystal; 1-Accounting; 1-Well File

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Merrion Oil & Gas Corporation

3. Address and Telephone No.

610 Reilly Avenue, Farmington, NM 87401

4. Location of Well (Footage, Sec., T., R., M., or Survey Des)

1650' fsl & 330' fel (NESE)
Section 15, T19N, R3W

FORM APPROVED

Budget Bureau No. 1004-0135
Expires: March 31, 19935. Lease Designation and Serial No.
NM-12012

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Media Entrada Unit

8. Well Name and No.

MEU No. 2

9. API Well No.

30-043-20087

10. Field and Pool, or Exploratory Area

Media Entrada

11. County or Parish, State

Sandoval County,
New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☒ Other Drilg & Completion

Horizontal Entrada

☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Nov. 9, 1995

TD: 5368'. Jar and work pipe. Globe basket plugged 5' above fish. TOH. TIH with globe basket, cross-over sub & bumper jars, pulled metal cutting. TIH w/globe basket cleaned to top of fish. TOH w/globe basket, recovered small metal pieces, milled 5-1/2" over collar. TIH with mill. Milled 5234' to 5238', milled plugged. TOH. TIH with overshot, jar & work pipe. MW 8.6, Visc. 44.

Nov. 10, 1995

TD: 5368'. TIH with tbq mill, jar and work pipe. TOH, overshot came off fish. TIH with tbq mill, milled 5238'-5256'. Pieces of metal sticking mill. TOH. TIH with globe basket milled down. TOH. Recovered several large pieces of metal. Start TIH with tbq mill. MW 8.6, Visc. 45.

Nov. 11, 1995

TD: 5368'. TIH, milled 2-3/8" tbq. Fished from 5256' to 5268'. TOH, Shut down changed out drilling line. Finished TOH. TIH with globe basket. TOH, recovered 7 pieces of metal. TIH with globe basket, work over fish plugged. TOH, recovered 2 large pieces of metal. MW 8.4, Visc. 42.

*** CONTINUED OTHER SIDE ***

14. I hereby certify that the foregoing is true and correct

Signed Steven S. DunnTitle Operations ManagerDate 12/1/95

(This space for Federal or State office use)

Approved by [Signature]
Conditions of approval, if any:Title Chief, Lands and Mineral ResourcesDate DEC 5 1995

Form 3100-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 19935. Lease Designation and Serial No.
NM-12012

6. If Indian, Allottee or Tribe Name

ON DIVISION

7. If Unit or CA, Agreement Designation
Media Entrada Unit8. Well Name and No.
MEU No. 2

9. API Well No.

10. Field and Pool, or Exploratory Area

Media Entrada11. County or Parish, State
**Sandoval,
New Mexico**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Merrion Oil & Gas Corporation

3. Address and Telephone No.

P. O. Box 840, Farmington, New Mexico 87499**(505) 327-9801**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**1650' fsl & 330' fel (NESE)
Section 15, T19N, R3W**

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐
- Notice of Intent
-
- ☒
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☐
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☒
- Other
- Drlg Rpt: -- Horizontal
Entrada**
-
- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 10-19-95 MIRU Pride Drlg Rig on 10/19/95. TIH with drill collars and drill pipe.
- 10-20-95 TIH with whipstock. Ran Gamma Ray and collar locator logs.. Set CIBP @ 4724'. PU Pipe. RU flowline.
- 10-21-95 TD 4722'. PU. TIH with 3" whipstock run directional survey. Orient and set whipstock at 96°. Mill window from 4710'-4718'.
- 10-22-95 TD 5036'. TOH with mill. Made 314' in 12-1/4 hrs drilling. TIH with Bit #1 Reed, 6-1/4", EHP, 62-A, SN, DM3371, and 2° motor. Drilled 4722'-5036'. Lost Build Rate start TOH steering tool stringer came loose. Bit #1 in at 4722', out at 5036'.

*** CONTINUED OTHER SIDE ***

14. I hereby certify that the foregoing is true and correct

Signature **Steven S. Dunn**Title **Operations Manager**Date **11/1/95**

(This space for Federal or State office use)

Approved by **[Signature]**Title **Chief, Lands and Mineral Resources**Date **DEC 5 1995**

Conditions of approval, if any: