Michael P. Grace II
Corinne Grace
P. O. BOX 1418
CARLSBAD, NEW MEXICO 88220
May 6, 1973

Mr. Jerry W. Long District Engineer United States Geological Survey Durango. Colorado

Dear Mr. Long:

Enclosed you will find 5 copies of Form 9-331 showing that we have plugged and abandoned the well which is located in Section 21, Tl2N, R3W., N.M.P.M. Sandoval County, New Mexico.

Also enclosed you will find a copy of the logs which were run on this well. If there is any more information that you need please feel free to call on me.

I am forwarding copies of the logs on to the Oil Conservation Commission in Aztec, New Mexico.

Sincerely yours,

Juanita L. Jones

jlj encl.

cc: Mr. Emery C. Arnold
Oil Conservation Commission
State of New Mexico
1000 Rio Brazos Road
Aztec, New Mexico

MAY 9 1973 OIL CON. COM. DIST. 3

					₹		
Form 9-331 (May 1963)	חבסגם'	UNITED STATES SUBMIT IN TRIPLICATE* RTMENT OF THE INTERIOR (Other instructions on re-			Form approved. Budget Bureau No. 42-R1421. 5. LEASE DESIGNATION AND SERIAL NO.		
	DEPAR			IOR verse side)		AND SERIAL NO.	
GEOLOGICAL SURVEY					NM 0349515 S. IF INDIAN, SILIOTEFE OR TRIBE NOVE		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)					San Croise, Supply	THE PARTY NAMED	
I. OIL GAS WELL OTHER					7. UNIT AGREEMENT N. N. A.	YAR	
2. NAME OF OPERATOR Michael P. Grace					8. FARM OR LEASE NA	ME	
3. ADDRESS OF OPERATOR					Sandy #1	· · · · · · · · · · · · · · · · · · ·	
P 0. Bo	x 1418, Ca	rlsbad, New M	.*	1 5			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)					10. FIELD AND POOL, O	R WILDCAT	
At surface Sec. 21, Tl2N., ReW., N.MP.M. Sandoval Co., N.Mex.					Wildcat		
1980	feet west	of east line,	330 Nort	th of South line	11. SEC., T., R., M., OR SURVEY OR AREA	BLK. AND	
•					Sec.21, T12N	, R3W., MMP	
14. PERMIT NO.	-	15. ELEVATIONS (S		, RT, GR, etc.)	12. COUNTY OF PARISE	1 13. STATS	
		60	17	<u> </u>	Sandoval	New Mexic	
TEST WATER SHU FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	NOTICE OF INT		NG	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	UENT REPORT OF: REPAIRING ALTERING C ABANDONME	ASING	
(Other)		Change Thank		(Norm: Report result	s of multiple completion eletion Report and Log fo	on Well	
17. DESCRIBE PROPOSEI proposed work. nent to this work	II wen is direc	PERATIONS (Clearly stationally drilled, give s	ite all pertinen subsurface loca	t details, and give pertinent dates tions and measured and true vertice	including entire to 3 de		
	-						
plug	gs at 700	-800' and 225-	- 325'. T	er USGS request with he well was then com between 121' and 22	pleted for fres	nt of a second	
	•			TO THE LEE WIND EE			
		•					
					FILM		
				/ K	LULLY LUI		
		-					
				i M	AY 9 1973 I		



	j		
18. I hereby certify that the foregoing is true and cor SIGNED CONTRACTOR CONTRACTOR	reotAgent	DATE 5/6/73	-
(This space for Federal or State office use)		•	ş
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	-