

## INSPECTION TICKET

DATE 7-16-74INSTALLATION CUBA #1 (DRY HOLE) LOCATION E-23-21N-1  
OPERATOR FRANKLIN, ASTON + FAIR INC. NEEDS SIGN \_\_\_\_\_LOCATION:CLEAN ☒ JUNKY \_\_\_\_\_ WEEDS \_\_\_\_\_

OIL &amp; WATER SPILL \_\_\_\_\_

EDGES CleanGENERAL APPEARANCE GoodPITS:DIKE GOOD FILLED NEEDS WORK \_\_\_\_\_

FENCE GOOD \_\_\_\_\_ NEEDS WORK \_\_\_\_\_

CONTAINS OIL \_\_\_\_\_ AMOUNT \_\_\_\_\_

CONTAINS WATER \_\_\_\_\_ AMOUNT \_\_\_\_\_

PRODUCTION EQUIPMENT:

SEPARATOR \_\_\_\_\_ DEHY \_\_\_\_\_ COMP \_\_\_\_\_

CLEAN \_\_\_\_\_ DIRTY \_\_\_\_\_ WEEDS \_\_\_\_\_

SAFE \_\_\_\_\_ FIRE HAZARD \_\_\_\_\_

PIPED TO PIT \_\_\_\_\_

PIPED TO TANK \_\_\_\_\_

LEAKS \_\_\_\_\_

FLOWS ON GROUND \_\_\_\_\_

FLOWS BEYOND PIT \_\_\_\_\_

TANKS:

NUMBER \_\_\_\_\_ SIZES \_\_\_\_\_

CLEAN \_\_\_\_\_ DIRTY \_\_\_\_\_

OVERFLOW TO PIT \_\_\_\_\_

LOAD LINE OK \_\_\_\_\_ PUDDLES OF OIL \_\_\_\_\_

LEAKS \_\_\_\_\_ FIRE HAZARD \_\_\_\_\_

FIRE WALLS \_\_\_\_\_ GOOD \_\_\_\_\_ NEED WORK \_\_\_\_\_

INSPECTED BY [Signature]

OWNER NOTIFIED BY PHONE, MAIL, DATE \_\_\_\_\_ OFFICE \_\_\_\_\_

OTHER REMARKS:PLA

NO DRY hole MARKER. DEAD MAN  
WIRES NOT CUT.