

THIRD INSPECTION
INSPECTION TICKET

DATE 6-2-76

INSTALLATION CUBA #1 (DRY HOLE) LOCATION E-23-2IN-10

OPERATOR FRANKLIN, ASTON & FAIR INC. NEEDS SIGN

POOL W.C. FORMATION

LOCATION:

CLEAN ☒ JUNKY ☐ WEEDS ☐

OIL & WATER SPILL ☐

EDGES CLEAN

GENERAL APPEARANCE GOOD

PITS:

DIKE GOOD FILLED NEEDS WORK ☐

FENCE GOOD ☐ NEEDS WORK ☐

CONTAINS OIL ☐ AMOUNT ☐

CONTAINS WATER ☐ AMOUNT ☐

PRODUCTION EQUIPMENT:

PUMP ☐ BELT GUARD ☐ FENCE ☐

SEPARATOR ☐ DEHY ☐ COMP ☐

CLEAN ☐ DIRTY ☐ WEEDS ☐

SAFE ☐ FIRE HAZARD ☐

PIPED TO PIT ☐ TANK ☐

LEAKS ☐

FLOWS TO PIT ☐ GROUND ☐

CATHODIC PROTECTION UNIT ☐

TANKS:

NUMBER ☐ SIZES ☐

CLEAN ☐ DIRTY ☐

OVERFLOW TO PIT ☐

LOAD LINE OK ☐ PUDDLES OF OIL ☐

LEAKS ☐ FIRE HAZARD ☐

FIRE WALLS ☐ GOOD ☐ NEED WORK ☐

FIRE WALL REQUIRED ☐ RECOMMENDED ☐

INSPECTED BY Chris. Holson

OWNER NOTIFIED BY MAIL, PHONE, DATE ☐ OFFICE ☐

OTHER REMARKS:

P+A

NO DRY HOLE MARKER. DEADMAN WIRES
NOT CUT.