


## DIRECTOR JOE D. RAMEY

## OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO 1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER PHIL R. LUCERO



EMERY C. ARNOLD

November 2, 1977

Mr. Jack A. Cole P. 0. Box 191 Farmington, New Mexico 87401

Re: Apache Flats #10

5-27-23N-4W

Dear Jack:

The revised location of the subject well will require the location to be surveyed and revised froms C-102 will be required; because,

- 1. You are moving to another quarter quarter section, and
- 2. You are changing drill tracts.

If there are questions, please contact us.


Yours very truly.

A. R. Kendrick

Supervisor, District #3

ARK:no

Enclosures



## UNITED STATES SURMIT IN TRIPLICATES Other Instructions on reDEPARTMENT OF THE INTERIOR verse side)

. !	Form aborevil, vo. 42-41424.  5. LEASE DESIGNATION AND SERVED NO.
۱ -	
	Contract 202
_	6. IF INDIAN, ALLOTTING OR TRIES NAME

111		
GEOL	oglCA'-	SURVEY

GEOLOGIO	- 0, 1, 2, 3, 4, 5
SUNDRY NOTICES AND REPORTS ON WEL (Do not use this form for proposals to drill or to deepen or plug back to a diffe Use "APPLICATION FOR PERMIT—" for such proposals.)	LS erent reservoir.  Jicarilla Apache 7. UNIT AGREEMENT NAME
1.  OIL GAS WELL OTHER  2. NAME OF OPERATOR  Jack A. Cole	S. FARM OR LEASE NAME Apache Flats 9. WELL NO.
P. O. Box 191, Farmington, New Mexico 874  P. O. Box 191, Farmington, New Mexico 874  4. LOCATION OF WELL (Report location clearly and in accordance with any State required See also space 17 below.)  At surface 1450/N and 990/W Sec. 27-T23N-R4W  /850  /90	10 10. FIELD AND POOL, OR WILDCAT  Wildcat Belland PC  11. SEC., T., E., M., OR BLK. AND  SURVEY OR ANDA  Sec. 27-T23N-R4W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.	Sandoval N. M.
TEST WATER SHUT-OFF PULL OR ALTER CASING FR.	Notice, Report, or Other Data  SUBSEQUENT REPORT OF:  REPAIRING WELL  ACTURE TREATMENT  ACTURE TREATMENT  ADDITING OR ACIDIZING  ABANDONMENT*

SHOOTING OR ACIDIZING (Other) Running Casing FRACTURE TREAT ABANDON\* (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Cemented 8 5/8" surface casing at 120' with Spudded well. 11-10-77: 100 sacks. Circulated cement.

Reached T.D. 2540'. Ran Schlumberger ES-Ind and GR-Density log. 11-13-77:

Ran 74 joints 4½", 10.50 lb. K-55 casing. Cemented casing at 2533 KB with 150 sacks 50-50 poxmix, 2% CaCl<sub>2</sub>, 7 lb. salt/sack. 11-14-77: FC @ 2490 KB. P.D. 11:15 A.M. WOC.

Operator מ, זיף זים SIGNED (This space for Federal or State office use) DATE -APPROVED BY CONDITIONS OF APPROVAL, IF ANY: