

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-7005

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

JAN 14 1977

1. OIL WELL GAS WELL OTHER Dry Hole

2. NAME OF OPERATOR U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

3. ADDRESS OF OPERATOR Dome Petroleum Corporation
c/o Minerals Management Inc.
501 Airport Dr., Suite 105, Farmington, N.M. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

14. PERMIT NO. 660' FSL, 2310' FWL, SEC. 3, T21N, R6W

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6891' GR 6903' KB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 3

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC. 3, T21N, R6W

12. COUNTY OR PARISH 13. STATE

Sandoval N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-5-77

Operator Plugged and Abandoned well as follows:

Plug No. 1 6540'-6690' (150') 75 sacks (Entrada)
 Plug No. 2 5519'-5669' (150') 75 sacks (Dakota)
 Plug No. 3 3495'-3645' (150') 75 sacks (Mancos)
 Plug No. 4 1420'-1570' (150') 75 sacks (Chacra)
 Plug No. 5 143'-243' (100') 50 sacks (Base Surface Pipe)
 Plug No. 6 30'-0' (30') 15 sacks (Surface)

Abandonment marker has been erected. Reserve Pit is fenced.
Location has not been restored.



18. I hereby certify that the foregoing is true and correct.

SIGNED J. Arnold Hill

TITLE Area Manager

Minerals Management Inc. DATE 1-10-77

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SK

*See Instructions on Reverse Side