

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Wildcat		5. LEASE DESIGNATION AND SERIAL NO.
2. NAME OF OPERATOR Petro-Lewis Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 1600 Broadway, Suite 1400, Denver CO 80202		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  2210' FNL, 2065' FEL, SW/4 NE/4 Section 27		8. FARM OR LEASE NAME Federal
14. PERMIT NO.		9. WELL NO. 7-27
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 6723' GL		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SW NE Section 27 - T19N-R3W
		12. COUNTY OR PARISH Sandoval
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input checked="" type="checkbox"/> Daily Drilling Reports	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Please find attached a weekly update of Petro-Lewis Corporation's daily drilling report.



18. I hereby certify that the foregoing is true and correct

SIGNED Ja. Win

TITLE Manager of Drilling & Production

DATE 1-5-77

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

DRILLING REPORT

Page 5

FEDERAL #7-27

SW NE Sec. 27, T19N-R3W  
Sandoval Co., New Mexico

- 12-30-76 Swbd well 8 hrs - total bbls: 134 - 8 B0, 126 BW - DC \$1450 - CC \$192,810
- 12-31-76 Put well back on pump - pumped 270 bbls in 20 hrs - made 8 B0 & 262 BW - 6-1/2 SPM, 100" stroke - shot FL, 1186' to fluid - DC \$560 - CC \$193,370
- 1-1-77 Pumped 24 hrs - 280 bbls total fluid - 10 B0 & 270 BW - DC \$200 - CC \$193,570
- 1-2-77 Pumped 24 hrs - 282 bbls total fluid - 10 B0 & 272 BW - DC \$200 - C \$193,770
- 1-3-77 Pumped well 24 hrs - 296 bbls total fluid, 286 BW, 10 B0 - increased SPM to 7 SPM - DC \$420 - CC \$194,190
- 1-4-77 Pumped well 18 hrs - worked on pumping unit & tank - total bbls 221 - 6 B0 & 215 BW - DC \$841 - CC \$195,031

35117 1722

1-1-77