Form 9-321 (May 1963)

UNITED STATES

Form approved. Budget Bureau No. 42-R1424.

	Rudget	Bures	IU N	D. 42-K	142
LEASE	DESIGN	ATION	AND	SERIAL	NO
4/4	1.4		./	/	

LITE OF THE LITER OF THE STATE			DESIGNATIO		4
EOLOGICAL SURVEY		MA	7-7	76	6
	_				

OIL GAS WELL OTHER WIldcat 2. NAME OF OPERATOR Petro-Lewis Corporation 3. ADDRESS OF OPERATOR 1600 Broadway, Suite 1400, Denver CO 80202 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Federal
OIL GAS WELL OTHER WILDCAT WELL SEAS OTHER WILDCAT OTHER WILDCATION OF WELL (Report location clearly and in accordance with any State requirements.*	S. FARM OR LEASE NAME
2. NAME OF OPERATOR Petro-Lewis Corporation 3. ADDRESS OF OPERATOR 1600 Broadway, Suite 1400, Denver CO 80202 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	
3. ADDRESS OF OPERATOR 1600 Broadway, Suite 1400, Denver CO 80202 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	
1600 Broadway, Suite 1400, Denver CO 80202 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	9. WELL NO.
See also appear 17 helent	7 10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	Wildcat
2210' FNL, 2065' FEL, SW/4 NE/4 Section 27	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARBA SW NE Section 27 - T19N-R3W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6723 GL	12. COUNTY OR PARISH 13. STATE Sandoval New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, or	
•	QUENT REPORT OF:
REPAIR WELL CHANGE PLANS (Other) (NOTE: Report result	REPAIRING WELL ALTERING CASING ABANDONMENT* Thing Report as of multiple completion on Well pletion Report and Log form.)
Please find attached a weekly update of Petro-Lewis Corporation report.	on's daily drilling
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Mgr. Drig. & Prod. (This space for Federal or State office use) APPROVED BY	DATE

DRILLING REPORT

FEDERAL #7-27 SW NE Sec. 27, T19N-R3W Sandoval Co., New Mexico

1-25-77

Page 6

RU - swbd on well - 40 bbls fluid back - no trace of cmt - RD swab -1-18-77 ran tbg anchor & pump in hole - set @ 1799' - DC \$2,203 - CC \$209,624 1-19-77 Started pump to pumping - ran three hrs - pumped 120 BW - pump stuck -DC \$680 - CC \$210.304 Laid down 7/8" rods & ran 1" rods - started pumping @ 6 PM - DC \$896 -1-20-77 CC \$211,200 Pumped 12 hrs - 40 B0 - 360 BW - pump went down - magneto wet - DC -0-1-21-77 Pumped 18 hrs - 380 BW - 5 BO - pump went down - magneto wet - DC \$200 -1-22-77 CC \$211,400 Pumped 10 hrs - 2 B0 - 100 BW - changing out magneto - DC \$200 - CC \$211,600 1-23-77 1-24-77 Pumped 10 hrs - 4 B0 - 220 BW - DC \$520 - CC \$212,120

Pumped 8 BO - 526 BW - DC \$200 - CC \$212,320