

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
Benson Mineral Group Inc.

3. ADDRESS OF OPERATOR 3200 Anaconda Tower,
555 17th. Street, Denver, Colo. 80202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1040' FNL, 1190' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: _____ SUBSEQUENT REPORT OF: _____

TEST WATER SHUT-OFF ☐

FRACTURE TREATMENT 1

SHOOT OR ACIDIZE ☐REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Change of Operator

SUBSEQUENT REPORT OF: 34

Drilling well

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

Benson Mineral Group is now the operator of this lease formerly operated by Dome Petroleum Corp. % Minerals Management Inc., 501 Airport Drive, Farmington, New Mexico. The thirteen-point development plan remains intact except that point 12 should be changed to contact Kurt Nelson, Benson Minerals Group, 501 Airport Drive, Farmington, New Mexico Telephone 505-325-9557.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE Area Manager
Minerals Mgm

DATE 6-16-78

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE _____

CONDITIONS OF APPROVAL IF ANY:

JUN 19 1978

***See Instructions on Reverse Side**

U. S. GEOLOGICAL SURVEY
DENVER, COLO.

0+5 USGS / 1- Dorne / 1- Lillon / 1- Trend / 1- Eff. Aquitaine / 1- Natl. Soc. Pipelines / 1- Benson Min. Exp. / 1- Fille