

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM - 5452	
2. NAME OF OPERATOR Dome Petroleum Corp - Benson Mineral Group, Inc. (Agent)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo	
3. ADDRESS OF OPERATOR Benson Mineral Group, Inc. 3200 Anaconda Tower, 555 17th Street, Denver, Colorado 80202		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FSL & 1810' FWL		8. FARM OR LEASE NAME Navajo 18	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6899 GR		10. FIELD AND POOL, OR WILDCAT Rusty Chacra Extension	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 18, T22N-R6W	
		12. COUNTY OR PARISH Sandoval	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	Attempt to set surface casing	<input type="checkbox"/>
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-30-78: Spud 11:00 A.M. 4-30-78. Drill 12 1/4" hole to 18', rig broke down.
5-1-78: Waiting on rig repair.
5-2-78: Waiting on rig repair and rain.
5-3-78: Rain washed out wash crossings.
5-4-78: Road impassable due to wash crossings.
5-5-78: Snow and rain made roads impassable.
5-6-78: Mud and Rain made roads impassable.
5-7-78: Mud made road impassable.
5-8-78: Waiting on mud to dry.
5-9-78: Waiting on mud to dry.
5-10-78: Waiting on dirt contractor to repair roads and wash crossings.

18. I hereby certify that the foregoing is true and correct


SIGNED Paul C. Ellison
(This space for Federal or State office use)

TITLE Production Manager

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side



RECEIVED
DATE May 11, 1978
MAY 15 1978

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.