Form	9-331	
(May	1963	ì

5-11-78:

## **UNITED STATES**

SUBMIT IN TRIPLICATE\*
(Other instructions on re-

Form approved. Budget Bureau No. 42-R1424.

SUBSEQUENT REPORT OF:

	DEPARTM	ENT OF THE INTERIOR verse side)	J. LEASE DESIGNATION	AND SERIAL NO.		
	GI	EOLOGICAL SURVEY	NM - 5452			
-		ES AND REPORTS ON WELLS s to drill or to deepen or plug back to a different reservoir. ION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME		
1.	OIL GAS X OTHER		7. UNIT AGREEMENT NA	ME		
2.	NAME OF OPERATOR		8. FARM OR LEASE NAM	(E		
	Dome Petroleum Corp - Benson Mineral Group, I 555 17th Street, Denver Location of Well (Report location cle See also space 17 below.) At surface 790' FSL & 1810' FWL	Rusty Chacra				
1.4	PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec 18, T22N			
14.	PERMIT AU.	6899' GR	Sandoval	New Mexico		
16.	Check App	propriate Box To Indicate Nature of Notice, Report,	or Other Data			

TEST WATER SHUT-OFF	 PULL OR ALTER CASING	 _	WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT	 MULTIPLE COMPLETE	 _	FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	 _	SHOOTING OR ACIDIZING		ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	 _	(Other) Set surf			
(Other)			(Note: Report rest Completion or Reco	ults o mple	of multiple completion on Well tion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5-12-78:	Waiting on rig repair.
5-13 <b>-</b> 78:	Waiting on rig repair.
5-14-78:	Waiting on rig repair.
5-15-78:	Waiting on rig repair.
5-16-78:	Waiting on rig repair.
5-17-78:	Waiting on rig repair.
5-18-78:	Waiting on rig repair.
5-19-78:	Waiting on rig repair.
5-20-78:	Rig down and move out surface casing rig. Move in and rig up Bayless Drilling.
5-21-78:	Commenced operations 21:30, 5-20-78. Drilling 12½" hole to 97'. 8 5/8"
	casing set at 96' with 120 sax of Class B cement with 2% CaCl. Circulate cement.
5-22-78:	Total depth 900', drilling/ Wait on cement for 8 hours. Pressure test

surface casing to 600 psi. Held OK. Drill out of surface sing at 96. with 64" bit.

18. I hereby cer and correct

NOTICE OF INTENTION TO:

Repair roads and wash crossings.

SIGNED C. Ellison TITLE \_ Production Manager DATE MAY 1978

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE

MAY 2 4 1978