MERRION OIL & GAS CORPORATION

Alemita No. 2 Sec. 28, T22N, R7W Sandoval Co., New Mexico

SLOPE TESTS

Depth	Hole Deviation
510	1/4
875	1/2
1250	1/2
1650	1/2

RECEIVED

State of New Mexico) County of San Juan)	ss	OIL CON. DIV. DIST. 3
I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.		
Subscribed and sworn be	fore me this 25th day	y cfMarch, 1985

Notary Public

My Commission Expires Oct. 28, 1985