IINITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 7998 เราะีสั 😹 เมื่อ
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	<u> </u>
reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME 🚆 💆 🚉
1. oil gas	Federal 3305 = 2 2 =
well well other	9. WELL NO. ំដ៏ខ្ញុំ 💆 🥞 💆 🧸
2. NAME OF OPERATOR Worldwide Exploration Consultants Inc.	1 ६५% है है है
worldwide Exploration Consultants Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR %K&A,Inc. Minerals Management	nt Wildcat 1000 T 200
Suite 105,501Airport Dr. Farmington, N.M.87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec 33, T20N, R4W 6
below.)	NMPM F F F F F F
AT SURFACE: 660FSL, 1650FEL Sec 33, T20N, R4W AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH Sandoval
AT TOTAL DEPTH:	
	14. API NO. 14 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	30-043-203231 = = = = = = = = = = = = = = = = = = =
The state of the s	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6770 GR 6 6 784 RKB 8 8 8 6 6 6
TEST WATER SHUT-OFF []	Tropy district to the control of the
FRACTURE TREAT	Control of the contro
SHOOT OR ACIDIZE	5 9 2 6 8 7 7 8 5 2
REPAIR WELL :	(NOTE: Report results of multiple completion or zone change on Form 9–330.)- 그 등 등 등을
MULTIPLE COMPLETE	Change on Form 9-350.7c The Section 64 to 10 to
CHANGE ZONES	원 등을 보고 그 그 한 지수는 다른 사람이 되었다.
ABANDON*	oldburth assign like rabs to chestics assignite that the chartes assignite that the
(other) Spud & Surface Casing	್ ನಿರ್ವಹ ಆ ಬ್ರಿಕ್ಕೆ ಕೈ ಗಳ ಬ್ರಿಕ್ಕಿ ಕೈ ಬ್ರಿಕ್ಕಿ ಕೈ
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	it to this work.)*
6-14-78 Spudded 13 3/4" hole at 2:30 P. M.	The second secon
6-15-78 Ran 5 joints, 221 ft., 95/8"O.D., 32.3	#, H-40, ST&C casing (new)
Set at 222 ft. and cemented with 200 s	
Plug down at 4:52 A.M. Cement Circulat	= u _m ?
·	
Pressure tested casing to 500 psi for	30 min. before drill-out
•	그 그 그는 그 회사활항체 사용 취취를 하는 것
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
Subsurface Safety Valve: Manu. and Type	
	1
18. I hereby certify that the foregoing is true and correct Area Manager	
SIGNED TITLE K&A Inc Min.	
(This space for Federal or State offi	ice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	ia withing Gerra
	一
	- BER 1985 원 - 1985년 - - 1985년 - 1985
AC-a lantamentiana de Processo	JUN-1 9 1978
*See Instructions on Reverse S	side .
USGS /1- Worldwide /1- File /1- Donne/1-Zilon	//- Svend /1-Elf Claudant // Mill. St. GEOLOGICAL SHRVEY
usus / Louis a / Tipe / Europia con	DURANGO, COLO
	2 3