

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
30-045-20328	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Helton Engineering & Geological Services, Inc.		Diamond Trail Ranch
3. Address of Operator		9. Well No.
860 Anaconda Tower, 555 - 17th Street, Denver, CO 80202		Brent No. 3
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>G</u> , <u>2200</u> FEET FROM THE <u>East</u> LINE AND <u>2550</u> FEET FROM		Entrada, Wildcat
THE <u>North</u> LINE, SECTION <u>19</u> TOWNSHIP <u>13N</u> RANGE <u>6E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
5668 GL		Sandoval

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned on May 30, 1978, as follows:

40 sacks from 2070 to 1937' (Entrada).
70 sacks from 1107 to 867' (Dakota).
10 sacks on top of surface pipe.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerome B. Weber TITLE Operations Mgr. DATE 6/18/78

APPROVED BY Not approved DATE _____
CONDITIONS OF APPROVAL, IF ANY: