Form 9-331 (May 1963)	DEPART	UNITED STATES MENT OF THE INTERI	SUBMIT IN TRIPLICATE (Other instructions on re-		
		GEOLOGICAL SURVEY	<b></b>	NM - 7246	
	SUNDRY NO	Sals to drill or to deepen or plug by ATION FOR PERMIT—" for such p	ack to a different reservoir.	6. IF INDIAN, ALLOTTEE OR	FRIBE NAME
I. OIL GAS X				7. UNIT AGREEMENT NAME	
WE'LL W	EDD OTHER	8. FARM OR LEASE NAME			
Benson Mineral Group, Inc.				Federal 28-21-5  9. WELL NO.  1	
3. ADDRESS OF OPERATOR 3200 Anaconda Tower, 555 17th Street, Denver, CO 80202					
4. LOCATION OF WI See also space At surface	ELL (Report location 17 below.)	Wildcat Committee R			
1140' F	SL and 1110'	FEL, Section 28-T21	N-R5W	11. SEC., T., R., M., OR BLK. A SURVEY OR AREA Section 28-T21	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE	
		6922 GR			NM
16.		ppropriate Box To Indicate N	•		
	NOTICE OF INTE	NTION TO:	SUBSE	QUENT REPORT OF:	
TEST WATER S	HUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TRE		MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	· -
SHOOT OR ACH	DIZE	ABANDON*	shooting or acidizing Set Pro	ABANDONMENT*	V
REPAIR WELL (Other)	<u></u>	CHANGE PLANS	(Note: Report resul	ts of multiple completion on Walletion Report and Log form.)	7ell
10	-8-78: Se	t 4½" casing at 1011'	with 150 sacks ceme	ent, circulate.	
18. I hereby certif	that the color	in Make and correct			
SIGNED	aul C. Ellis	lish TITLE P	roduction Manager	DATE_October	20, 1978
	or Federal or State o			DEGELVE	
APPROVED I		TITLE		DATE	
	OF APPROVAL, IF	ANY:		007 9 9 1070	

OCT 23 1978