

Sep - OK
Tank - OK

AND OIL & GAS ADMINISTRATION

REV 1 2 1955

AND OIL & GAS ADMINISTRATION

REV 12 1980

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 07/10/97 Date Completed: 07/16/97
 Remediation Method: Excavation X Approx. cubic yards 50
 (Check all appropriate sections) Landfarmed X Insitu Bioremediation _____
 Other _____

Remediation Location: Onsite X Offsite _____
 (i.e. landfarmed onsite, name and location of offsite facility) _____

General Description of Remedial Action: EXCAVATE PIT TO OVM LEVEL OF OPPM
SAMPLE 1 BELOW EXCAVATION SAMPLE 2 4 POINT COMPOSITE SIDES

Groundwater Encountered: No X Yes _____ Depth _____

Final Pit: Sample location #1 - 1' BELOW EXCAVATION #2 - 1' PENETRATION EACH SIDE
 Closure Sampling: ANALYSIS - FIELD HEADSPACE AND TPH ALL SAMPLES
 (if multiple samples, attach sample results and diagram of sample locations and depths) Sample depth 7 FEET
 Sample date 07/16/97 Sample time 07:00

Sample Results

Soil: Benzene (ppm) _____ Water: Benzene (ppb) _____
 Total BTEX (ppm) _____ Toluene (ppb) _____
 Field Headspace (ppm) S- 0 B-0 Ethylbenzene (ppb) _____
 TPH (ppm) S-432 B-248 Total Xylenes (ppb) _____

Groundwater Sample: Yes _____ No _____ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 8/21/97 PRINTED NAME BRADLEY W. SALZMAN

SIGNATURE Bradley W. Salzman AND TITLE AGENT

AFTER REVIEW OF THE PIT CLOSURE INFORMATION, PIT CLOSURE IS APPROVED IN ACCORDANCE TO THE JICARILLA APACHE TRIBE PIT CLOSURE ORDINANCE.

APPROVED: YES X NO _____ (REASON) _____

SIGNED: Karen G. Callicott DATE: 8/27/97



Amoco Production Company




ENGINEERING CHART

Sheet No. _____ Of _____
File _____
Appn _____
Date _____
By _____

SUBJECT RODDY PRODUCTION - PIT CLOSURE

FIELD NOTES

WELL NAME: CHACON JICARILLA APACHE
D-103 SEPARATOR



SAMPLE ANALYSIS		
	OVM PPM	TPH PPM
A ₁	8	A-D 432
B ₁	4	
C ₁	0	
D ₁	0	
E ₁	2	248
A ₂		
B ₂		
C ₂		
D ₂		
E ₂		
A ₃		
B ₃		
C ₃		
D ₃		
E ₃		

— — — ORIGINAL
— — — EXCAVATED

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

July 18, 1997

Mr. Bradley Salzman
Roddy Production Company
P.O. Box 2221
Farmington, New Mexico 87499

Project No.: 97300-44

Dear Mr. Salzman,

Enclosed are the analytical results for the samples taken from the location identified as "Jicarilla Pits - Chacon Jicarilla". Eight soil samples were collected from the referenced location by Roddy Production personnel 07/16/97, and delivered to the Envirotech Laboratory on 07/16/97 for Total Petroleum Hydrocarbon (TPH) analysis per USEPA Method 8015, Modified.

The samples were documented on Envirotech Chain of Custody No. 5303, and assigned Laboratory Nos. B660 (D-103 Sep. Sides), B661 (D-103 Sep. Bot), B662 (D-103 Tank Sides), B663 (D-103 Tank Bot), D664 (D-110 Sep. Sides), D665 (D-110 Sep. Bot), B666 (D-110 Tank Sides), and B667 (D-110 Tank Bot) for tracking purposes.

Should you have any questions or require additional information, please do not hesitate to contact us at (505) 632-0615.

Respectfully Submitted,
Envirotech, Inc.



Stacy W. Sandler
Environmental Scientist/Laboratory Manager

enclosure

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Roddy Production	Project #:	96300-44
Sample ID:	D-103 Sep. Sides	Date Reported:	07-18-97
Laboratory Number:	B660	Date Sampled:	07-16-97
Chain of Custody No:	5303	Date Received:	07-16-97
Sample Matrix:	Soil	Date Extracted:	07-16-97
Preservative:	Cool	Date Analyzed:	07-17-97
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	432	0.1
Total Petroleum Hydrocarbons	432	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, July 1992.

Comments: **Jicarilla Pits.**
Chacon Jicarilla.


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Roddy Production	Project #:	96300-44
Sample ID:	D-103 Sep. Bot.	Date Reported:	07-18-97
Laboratory Number:	B661	Date Sampled:	07-16-97
Chain of Custody No:	5303	Date Received:	07-16-97
Sample Matrix:	Soil	Date Extracted:	07-16-97
Preservative:	Cool	Date Analyzed:	07-17-97
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	248	0.1
Total Petroleum Hydrocarbons	248	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, July 1992.

Comments: Jicarilla Pits.
Chacon Jicarilla.


Analyst


Review

CHAIN OF CUSTODY RECORD

Client/Project Name			Project Location		ANALYSIS/PARAMETERS										
Roddy Production			TICORILLA PITS												
Sampler (Signature) <i>B. J. Seligman</i>			Chain of Custody Tape No. 96305-44												
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers						Remarks				
CUACON TICORILLA	7/15/97	07:10	Blue 0	SOIL	1	1									
D-103 SEP. SIDES	"	07:15	Blue 1	"	1	1									
D-103 SEP. BOT	"	07:20	Blue 2	"	1	1									
D-103 TANK SIDES	"	07:25	Blue 3	"	1	1									
D-103 TANK BOT.	"	07:45	Blue 4	"	1	1									
D-110 SEP. SIDES	"	07:50	Blue 5	"	1	1									
D-110 SEP. BOT.	"	07:55	Blue 6	"	1	1									
D-110 TANK SIDES	"	08:00	Blue 7	"	1	1									
D-110 TANK BOT.	"														
All samples received and analyzed															
Relinquished by: (Signature) <i>B. J. Seligman</i>			Date	Time	Received by: (Signature) <i>Chick Watts</i>			Date			Time				
			7/16/97	11:15				7-16-97			11:15				
Relinquished by: (Signature)					Received by: (Signature)										
Relinquished by: (Signature)					Received by: (Signature)										

ENVIROTECH INC.
 5796 U.S. Highway 64-3014
 Farmington, New Mexico 87401
 (505) 632-0615

**JICARILLA APACHE TRIBE
ENVIRONMENTAL PROTECTION OFFICE
P.O. BOX 507
DULCE, NEW MEXICO 87528**

SUBMIT 1 COPY TO
NATURAL RESOURCE DEPT
AND OIL & GAS ADMINISTRATION

PIT REMEDIATION AND CLOSURE REPORT

Operator: RODDY PRODUCTION **Telephone:** 505-325-5750

Address: P.O. BOX 2221 FARMINGTON, NM 87499

Facility or Well Name: CHACON JICARILLA APACHE D NO 103

Location: Unit or Qtr/Qtr Sec C Sec 35 T 23NR 3W County RIO ARriba NM

Pit Type: Separator ☐ Dehydrator ☐ Other TANK

Land Type: _____

Pit Location: Pit dimensions: length 15', width 15', depth 3'
(Attach diagram)

Reference: wellhead X, other _____

Footage from reference: 150

Direction from reference: N80W Degrees _____ East North _____
_____ of _____ West South _____

Depth To Groundwater:

(Vertical distance from
contaminants to seasonal
high water elevation of
groundwater)

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 points) 0

Distance to an Ephemeral Stream

(Downgradient dry wash greater than
ten feet in width)

Less than 100 feet (10 points)
Greater than 100 feet (0 points) 0

Distance to Nearest Lake, Playa, or Watering Pond

(Downgradient lakes, playas and
livestock or wildlife watering ponds)

Less than 100 feet (10 points)
Greater than 100 feet (0 points) 0

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or: less than
1000 feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 100 feet (20 points)
100 feet to 1000 feet (10 points)
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 07/11/97 Date Completed: 07/16/97

Remediation Method: Excavation X Approx. cubic yards 30
(Check all appropriate sections) Landfarmed X Insitu Bioremediation _____
Other _____

Remediation Location: Onsite X Offsite _____
(i.e. landfarmed onsite,
name and location of
offsite facility) _____

General Description of Remedial Action: EXCAVATE PIT TO OVM LEVEL OF OPDM
SAMPLE 1 4' BELOW EXCAVATION SAMPLE 2 4 POINT COMPOSITE SIDES

Groundwater Encountered: No X Yes _____ Depth _____

Final Pit: Sample location #1 - BELOW EXCAVATION #2 - 1' PENETRATION EACH SIDE
Closure Sampling: ANALYSIS - FIELD HEADSPACE AND TPH ALL SAMPLES
(if multiple samples, attach sample results and diagram of sample locations and depths) Sample depth 7 - FEET
Sample date 07/16/97 Sample time 07:20

Sample Results

Soil: Benzene (ppm) _____ Water: Benzene (ppb) _____
Total BTEX (ppm) _____ Toluene (ppb) _____
Field Headspace (ppm) S-0 B-0 Ethylbenzene (ppb) _____
TPH (ppm) S-355 B-388 Total Xylenes (ppb) _____

Groundwater Sample: Yes _____ No _____ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 8/21/97 PRINTED NAME BRADLEY W. SALZMAN

SIGNATURE Bradley W. Salzman AND TITLE AGENT

AFTER REVIEW OF THE PIT CLOSURE INFORMATION, PIT CLOSURE IS APPROVED IN ACCORDANCE TO THE JICARILLA APACHE TRIBE PIT CLOSURE ORDINANCE.

APPROVED: YES X NO _____ (REASON) _____

SIGNED: Karina X. Nallado DATE: 8/27/97



Amoco Production Company




ENGINEERING CHART

Sheet No. _____ Of _____
File _____
Appn _____
Date _____
By _____

SUBJECT RODDY PRODUCTION - PIT CLOSURE

FIELD NOTES

WELL NAME: CNACON JICARILLA APACNE
D-103 TANK



— — — ORIGINAL
===== EXCAVATED

SAMPLE ANALYSIS		
	OVM PPM	TPH PPM
A ₁	0	A-D 355
B ₁	7	
C ₁	0	
D ₁	1	
E ₁	0	388
A ₂		
B ₂		
C ₂		
D ₂		
E ₂		
A ₃		
B ₃		
C ₃		
D ₃		
E ₃		

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

July 18, 1997

Mr. Bradley Salzman
Roddy Production Company
P.O. Box 2221
Farmington, New Mexico 87499

Project No.: 97300-44


Dear Mr. Salzman,

Enclosed are the analytical results for the samples taken from the location identified as "Jicarilla Pits - Chacon Jicarilla". Eight soil samples were collected from the referenced location by Roddy Production personnel 07/16/97, and delivered to the Envirotech Laboratory on 07/16/97 for Total Petroleum Hydrocarbon (TPH) analysis per USEPA Method 8015, Modified.

The samples were documented on Envirotech Chain of Custody No. 5303, and assigned Laboratory Nos. B660 (D-103 Sep. Sides), B661 (D-103 Sep. Bot), B662 (D-103 Tank Sides), B663 (D-103 Tank Bot), D664 (D-110 Sep. Sides), D665 (D-110 Sep. Bot), B666 (D-110 Tank Sides), and B667 (D-110 Tank Bot) for tracking purposes.

Should you have any questions or require additional information, please do not hesitate to contact us at (505) 632-0615.

Respectfully Submitted,
Envirotech, Inc.



Stacy W. Sendler
Environmental Scientist/Laboratory Manager

enclosure

SWS/sws

970481b8.wpd

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Roddy Production	Project #:	96300-44
Sample ID:	D-103 Tank Sides	Date Reported:	07-18-97
Laboratory Number:	B662	Date Sampled:	07-16-97
Chain of Custody No:	5303	Date Received:	07-16-97
Sample Matrix:	Soil	Date Extracted:	07-16-97
Preservative:	Cool	Date Analyzed:	07-17-97
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	355	0.1
Total Petroleum Hydrocarbons	355	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, July 1992.

Comments: Jicarilla Pits.
Chacon Jicarilla.


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Roddy Production	Project #:	96300-44
Sample ID:	D-103 Tank Bot.	Date Reported:	07-18-97
Laboratory Number:	B663	Date Sampled:	07-16-97
Chain of Custody No:	5303	Date Received:	07-16-97
Sample Matrix:	Soil	Date Extracted:	07-16-97
Preservative:	Cool	Date Analyzed:	07-17-97
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	388	0.1
Total Petroleum Hydrocarbons	388	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, July 1992.

Comments: Jicarilla Pits.
Chacon Jicarilla.


Analyst


Review

CHAIN OF CUSTODY RECORD

Client/Project Name			Project Location		ANALYSIS/PARAMETERS									
Sampler (Signature)			Chain of Custody Tape No.		Remarks									
Sample No./ Identification			Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers							
Cuacon Jicorilla			7-16-97	07:10	Blue 0	SOIL	1	1						
D-103 SEP. SIDES			"	07:15	Blue 1	"	1	1						
D-103 SEP. BOT			"	07:20	Blue 2	"	1	1						
D-103 TANK SIDES			"	07:25	Blue 3	"	1	1						
D-103 TANK BOT.			"	07:45	Blue 4	"	1	1						
D-110 SEP. SIDES			"	07:50	Blue 5	"	1	1						
D-110 SEP. BOT.			"	07:55	Blue 6	"	1	1						
D-110 TANK SIDES			"	08:00	Blue 7	"	1	1						
D-110 TANK BOT.			"											
All samples received and intact and														
Relinquished by: (Signature)			Date	Time	Received by: (Signature)			Date						
B. B. Salzman			7-16-97	11:15	Chick Heets			7-16-97 11:15						
Relinquished by: (Signature)			Received by: (Signature)											
Relinquished by: (Signature)			Received by: (Signature)											

ENVIROTECH INC.

5796 U.S. Highway 64-3014

Farmingington, New Mexico 87401

(505) 632-0615

JICARILLA APACHE TRIBE
ENVIRONMENTAL PROTECTION OFFICE
P.O. BOX 507
DULCE, NEW MEXICO 87528

ON-SITE SOIL REMEDIATION REPORT

RECEIVED
NOV 12 1999
DULCE, NM

Operator: Roddy Production Telephone: (505) 325-5750

Address: P.O. Box 2221, Farmington, NM 87499

Facility or Well Name: Chacon Jicarilla Apache D-103

Location: Unit or Qtr/Qtr Sec C Sec 35 T 23N R 3W County Sandoval

Land Type: Range

Date Remediation Started: July 1997 Date Completed: September 1999

Remediation Method: Landfarmed X Approx. cubic yards 80

Composed

Other

Depth to Groundwater: (pts) 0

Distance to an Ephemeral
Stream (pts) 0

Distance to Nearest Lake,
Playa, or Watering Pond (pts) 0

Wellhead Protection Area (pts) 0

Distance to Surface Water (pts) 0

RANKING SCORE
(TOTAL POINTS): 0

Final Closure Sampling:

Sampling Date: 9/14/99 Time: 12:10

Sample Results:

Field Headspace (ppm) 15.2

TPH (ppm) 221 Method 8015

Other:

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE: October 4, 1999 PRINTED NAME B.W. Salzman

SIGNATURE B.W. Salzman AND TITLE Agent


AFTER REVIEW OF THE SOIL REMEDIATION INFORMATION. ON-SITE SOIL REMEDIATION IS APPROVED IN ACCORDANCE TO THE JICARILLA APACHE TRIBE PIT CLOSURE ORDINANCE.

APPROVED: YES X NO (REASON)

SIGNED: K.C. Mando DATE: 10-20-99

Client : Roddy Production

Date Started : July 1997 Date Completed : September 1999

Location: <u>Chacon Jicarilla Apache D-103</u>		Overview of Landfarm and Sampling :	
Quad: <u>C</u>	Section: <u>35</u>		
Township: <u>23 N</u>	Range: <u>3 W</u>		
Pits: Separator and Tank			
Reference:			
LF #1: 40' northwest of wellhead			
LF #2: 70' southwest of wellhead			
LF #3: 120' south of wellhead			
Size: LF #1: Approx. 50'x50'x1' deep			
LF #2: Approx. 30'x15'x6" deep			
LF #3: Approx. 40'x20'x6" deep			
Yds: LF #1: 60 cubic yards			
LF #2: 5 cubic yards			
LF #3: 15 cubic yards			
1 5 - Point Composite(s)			
Sample #	Location	OVM	
1	Comp 1	15.2	
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
Comments: <u>A sample from composite # 1 was sent to Envirotech for TPH 8015 analysis.</u>			

Ranking Score : 0 Closure Standard : 5000 ppm

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

September 17, 1999

Mr. Brad Salzman
Roddy Production Company
P.O. Box 2221
Farmington, New Mexico 87499

Project No.: 99063
Job No.: 906301

Dear Mr. Salzman,

Enclosed are the analytical results for the samples collected from the location designated as "Jicarilla Land Farms". Two soil samples were collected by Roddy Production Company designated personnel on 09/14/99, and delivered to the Envirotech laboratory on 09/15/99 for Total Petroleum Hydrocarbons (TPH) analysis per USEPA Method 8015 Modified.

The samples were documented on Envirotech Chain of Custody No. 7341 and assigned Laboratory Nos. G074 (JAT D-103) and G075 (JAT D-107) for tracking purposes. The samples were extracted and analyzed on 09/16/99 using USEPA or equivalent methods.

Should you have any questions or require additional information, please do not hesitate to contact us at (505) 632-0615.

Respectfully submitted,
Envirotech, Inc.



Stacy W. Sender
Environmental Scientist/Laboratory Manager

enclosure

SWS/sws/99063/906301.lb2/wpd

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

**EPA METHOD 8015 Modified
Nonhalogenated Volatile Organics
Total Petroleum Hydrocarbons**


Client:	Roddy Proc. Co.	Project #:	906301
Sample ID:	JAT D-103	Date Reported:	09-16-99
Laboratory Number:	G074	Date Sampled:	09-14-99
Chain of Custody No:	7341	Date Received:	09-15-99
Sample Matrix:	Soil	Date Extracted:	09-16-99
Preservative:	Cool	Date Analyzed:	09-16-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	13.1	0.2
Diesel Range (C10 - C28)	208	0.1
Total Petroleum Hydrocarbons	221	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: Jicarilla Land Farms.


Analyst


Review

CHAIN OF CUSTODY RECORD

7341

Client / Project Name			Project Location		ANALYSIS / PARAMETERS																	
Robby Prod. Co.			TICORILLO LEAD FORMS																			
Sampler: B.W. Sackman			Client No. 906301																			
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers	EPA 8015					Remarks											
JAT P-103	9-14-99	12:10	6074	Soil	1	✓																
JAT D-107	9-14-99	12:30	6075	Soil	1	✓																
Relinquished by: (Signature)		Date		Time		Received by: (Signature)		Date		Time												
<i>B.W. Sackman</i>		9-15-99		9:10		<i>Debra L. Quinn</i>		9-15-99		9:10												
Relinquished by: (Signature)						Received by: (Signature)																
Relinquished by: (Signature)						Received by: (Signature)																
ENVIROTECH INC. 5796 U.S. Highway 64 Farmington, New Mexico 87401 (505) 632-0615 <table border="1"> <thead> <tr> <th colspan="3">Sample Receipt</th> </tr> </thead> <tbody> <tr> <td>Received Intact</td> <td>Y</td> <td>N</td> </tr> <tr> <td>Cool - Ice/Blue Ice</td> <td>✓</td> <td></td> </tr> </tbody> </table>														Sample Receipt			Received Intact	Y	N	Cool - Ice/Blue Ice	✓	
Sample Receipt																						
Received Intact	Y	N																				
Cool - Ice/Blue Ice	✓																					