Form 9-331

REPAIR WELL

(Other)

UNITED STATES

SUBMIT IN TRIPLICATE.

(Other) Running Casing

Form approved.

| DEPARTMENT OF THE INTERIOR COther GEOLOGICAL SURVEY | Instructions on reside) 5. LEASE DESIGNATION AND SERIAL M SF081160-F | | | |
|---|--|----|--|--|
| SUNDRY NOTICES AND REPORTS ON WEL (Do not use this form for proposals to drill or to deepen or plug back to a differ Use "APPLICATION FOR PERMIT". " for such proposals.) | LS 6. IF INDIAN, ALLOTTEE OR TRIBE NAM | МЕ | | |
| OIL GAS OTHER | 7. UNIT AGREEMENT NAME | | | |
| NAME OF OPERATOR | 8. FARM OR LEASE NAME | | | |
| Noel Reynolds dba Torreon Oil Co. | San Luis Federal | | | |
| ADDRESS OF OPERATOR | 9. WELL NO. | | | |
| Box 356 Flora Vista N.M. 87415 | 3 | | | |
| LOCATION OF WELL (Report location clearly and in accordance with any State require See also space 17 below.) At surface 2164' fsl. 1600' fel. | Too will have tools, on willbear | • | | |
| 2164' fsl, 1600' fel, | San Luis Mesa Verd 11. sec., t., r., m., or blk. and survey or area | œ. | | |
| | Sec. 21 T18N R3W | | | |
| 4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | 12. COUNTY OR PARISH 13. STATE | | | |
| 6690 GR | Sandoval N.M. | | | |
| 6. Check Appropriate Box To Indicate Nature of N | otice, Report, or Other Data | | | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | | | |
| TEST WATER SHUT-OFF PULL OR ALTER CASING WATER | R SHUT-OFF REPAIRING WELL | | | |
| FRACTURE TREAT MULTIPLE COMPLETE FRACT | URE TREATMENT ALTERING CASING | | | |
| SHOOT OR ACIDIZE ABANDON* SHOOT | FING OR ACIDIZING ABANDONMENT* | | | |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Contractor moved on location 8/6/78 8AM drilled 31 ft. 8 5/8 hole set 31 ft. 7" 20# casing and circulated cement.

Started drilling with air at 10 PM drilled to 595' encountered show of oil no water drilled an additional $11\frac{1}{2}$ ft. to $606\frac{1}{2}$ ' had good amount of oil in hole. approx 1 bbl. per hr.

Ran $606\frac{1}{2}$ ' $4\frac{1}{2}$ " 10.50 # casing , with 25' slotted liner and Baker umberella cement retainer 25' off bottom.

Moved rig off, waiting for completion unit.

CHANGE PLANS

| Formations: | Cliffhouse | Surface | to | 41 ft. |
|-------------|------------|---------|----|---|
| | Menefee | 41 ft. | to | 606½ ft. |
| | | | | SEP 15 1978 OIL CON. COM. DIST. 3 |

| 18. I hereby certify that the foregoing is true and correct | | |
|---|----------|------|
| SIGNED LECT As a set (| TITLE OF | DATE |
| (This space for Federal or State office use) | | |
| APPROVED BY CONDITIONS OF APPROVAL, IF ANY: | TITLE | DATE |