

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)


1. oil ☐ well ☐ gas ☐ well ☐ other ☒ Injection Well2. NAME OF OPERATOR
Torreon Oil Company3. ADDRESS OF OPERATOR
9616 Westpark Dr. Benbrook, TX 761264. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2278' North of South line
AT TOP PROD. INTERVAL: 2296 East of West Line
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Shut - in well ☒

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☒5. LEASE
SF 081161-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
San Luis Federal

9. WELL NO.

2

10. FIELD OR WILDCAT NAME
San Luis Mesa Verde11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 21 T 18N R 3W12. COUNTY OR PARISH | 13. STATE
Sandoval | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6749

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well is shut-in as of December 29, 1981, awaiting approval to inject water.

Subsurface Safety Valve: Mand. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Manager

DATE 3/4/82

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 10 1982

FARMINGTON DISTRICT

BY

*See Instructions on Reverse Side

NMOCC