

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424

SUNDY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT..." for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Wildcat		5. LEASE DESIGNATION AND SERIAL NO. NM 13948-A
2. NAME OF OPERATOR Rijan Oil Company, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
3. ADDRESS OF OPERATOR 20 First Plaza, Suite 402, Albuquerque, New Mexico 87102		7. UNIT AGREEMENT NAME N/A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1650' fwl, 2310' fsl		8. FARM OR LEASE NAME <i>Federal 27</i> Rijan Oil Company, Inc.
14. PERMIT NO. U.S.G.S.		9. WELL NO. <del>Federal</del> # 1- <del>27</del>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6734' GR		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T19N, R3W, NMPM
		12. COUNTY OR PARISH Sandoval
		13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) Supplemental

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Spudded 12 $\frac{1}{2}$ " hole @9:30 PM, 2/4/79.  
Drilled to 223'. 3/4" @221'. Ran 5  
joints 9 5/8" 32# H-40 casing. T.E.  
198.52', set @210'. Cemented w/190 sx  
Class B w/3% CaCl<sub>2</sub>. POB 5:30 AM 2/5/79.  
Cement circulated. Tested w/450 psi for  
30 min. and held ok.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Petroleum Engineer

DATE

2-5-79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side