

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas well ☐ other Abandonment

2. NAME OF OPERATOR

Wm. B. MARTIN JR

3. ADDRESS OF OPERATOR

1300 West Alvejo Farmington N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 360' s1/4 270' w1 Sec 29 T17N-R4W

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON\* ☒(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED

OCT 29 1979

U. S. GEOLOGICAL SURVEY  
DURANGO, COLO.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9/2/79 Drilled - hole dry. Sandstone stained f w/odor 95-100, 105-110

No Fluid - waited 2 hours blew hole no fluid

9/13/79 Logged No Fluid Logged depth 117.5; Drilled depth 120'

9/10/79 Plumbed hole; no fluid

+ Plug

25 cement 0-25' ~ 2.87 ~ 3 sacks

Cutting 25-70'

Set 25' cement 90-117.5 ~ 3 sacks

Subsurface Safety Valve: Manu. and Type KloneSet @ 00' Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Wm. B. Martin Jr TITLE Operator DATE 9/17/79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: