Forth	9-331
(Mav	1963)

OIL GAS WELL

3. ADDRESS OF OPERATOR

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

RIJAN OIL COMPANY, INC.

1650' fsl, 2310' fel

2. NAME OF OPERATOR

UNITED STATES SUBMIT IN TRIPLICATES Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

5.	LEASE	DESIGNATION	AND	SERIAL

GEOLOGICAL SURVEY	VEY
-------------------	-----

CHIMIDDA	NOTICES	AND	REPORTS	ON	WELLC
SUNDKY	NOHES	ANU	REPURIS	UN	WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

NM-11772

Rijan Oil Company, Inc.

9. WELL NO.

Federal 26 #

10. FIELD AND POOL, OR WILDCAT

Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 26,T19N,R3W, NMPM

12. COUNTY OR PARISH 13. STATE

Sandoval

New Mexico

14. PERMIT NO.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6727' GR

NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE

ABANDON*

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface

CHANGE PLANS

OTHER

20 First Plaza, Suite 402, Albuquerque, NM

SUBSEQUENT REPORT OF : WATER SHUT-OFF

FRACTURE TREATMENT SHOOTING OR ACIDIZING

ALTERING CASING ABANDONMENT*

REPAIRING WELL .

(Other) surface casing (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertiproposed work. If nent to this work.) *

Spudded 14 3/4" hole 9:30 P.M. 5/17/80. Drilled to 200', ran 4 jts. 10 3/4", 36#, H, casing w/Texas Pattern Guideshoe. T.E. 182', set @194'. Cemented w/220 sx. Class B cement w/2% CaCl2. Cement circulated. P.O.B. 12:15 P.M. 5/18/80. After 14 hrs, tested casing w/800 P.S.I. for 30 min. Held ok.

RECEIVED

MAY 2 3 1987

U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

nuc

TITLE Petroleum Engineer

DATE <u>5/20/80</u>

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE

FARMINGTON DISTRICT MX Kuc

*See Instructions on Reverse Side