

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Jack A. Cole
3. ADDRESS OF OPERATOR
P. O. Box 191, Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1080/N and 1110/E Sec. 7
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	☐	☐
FRACTURE TREAT	☒	☐
SHOOT OR ACIDIZE	☐	☐
REPAIR WELL	☐	☐
PULL OR ALTER CASING	☐	☐
MULTIPLE COMPLETE	☐	☐
CHANGE ZONES	☐	☐
ABANDON*	☐	☐
(other) Running Casing		X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-7-80 Reached TD 1534'. Ran 47 joints 4½", 10 lb. K55 casing. Cement: 500 gallons mud flush followed by 50 sacks 65/35 Pozmix, 12% gel with 6½ lbs. Gilsonite per sack followed by 115 sacks 50/50 Pozmix, 2% gel, with 6½ lbs. Gilsonite and 6 lbs. salt per sack. Spotted 250 gallons acetic acid on plug. Float at 1474'. Plug down 1:00 P.M. Cement circulated.

Prep to sand water frac treat through casing perforations w/30,000 gals. water, 40,000 lbs. 20-40 lb. sand.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Jack A. Cole TITLE Operator

DATE Mar 11 1980

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.