	UNITED STATES		5. LEASE
DEPARTMENT OF THE INTERIOR			NM 27431 7 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
GEOLOGICAL SURVEY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	.010401		中華調整 ひに変地算
CHAIDDY MOTIC	ES AND REPORTS ON	WELLS	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for	oosals to drill or to deepen or plug ba or such proposals.)	ck to a different	8. FARM OR LEASE NAME 2 223
1 -: 1			DOME FEDERAL 27-17-3
1. oil gas well	other		9 WELL NO =
2. NAME OF OPERATOR	R		1 2 3 4 5 5
DOME PETROLEUM			10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERA			WILDCAT FOR THE STATE OF THE ST
	Suite 107, Farmingto	n NM	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4 LOCATION OF WELL	(REPORT LOCATION CLEARLY.	See space 17	AREA
below.)	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Sec. 27, T17N, R3W
AT SURFACE: 1650' FNL, 2000' FEL AT TOP PROD. INTERVAL:		12. COUNTY OR PARISH 13. STATE	
		Sandoval New Mexico	
AT TOTAL DEPTH:			14. API NO. 5 - 2 7 7 2 2 2 1
16. CHECK APPROPRIAT	E BOX TO INDICATE NATURE	OF NOTICE,	T
REPORT, OR OTHER DATA			15. ELEVATIONS (SHOW DF, KDB, AND WD)
			6340' GR
REQUEST FOR APPROVA	L TO: SUBSEQUENT RE	PORT OF:	+9\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
TEST WATER SHUT-OFF			្រុំខ្លួល គឺ ស្នើបា
FRACTURE TREAT SHOOT OR ACIDIZE			
REPAIR WELL	H H		(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING			change on Form 9–330.)
MULTIPLE COMPLETE			그 그 그 그 이 그 이 이 이 회사 회사 회사 회사를 들어 들어
CHANGE ZONES			그 그 그 그는 그를 잃었다. 그는 그를 다고 있다.
ABANDON*			
(other)			
17. DESCRIBE PROPOSE	D OR COMPLETED OPERATION	S (Clearly state	e all pertinent details, and give pertinent dates,
including estimated of	date of starting any proposed wo	ork. If well is d	lirectionally drilled, give subsurface locations and
measured and true ve	ertical depths for all markers and candoned Well As Follo	vanes peruner	int to this work.)
Plug No.	Interval	Feet	t Sacks Cement
			
1	3483-3336	150	는 등록 중 (60 - 축구 왕조중)
2	2400-2200	200	(175 275 - 立) 直蓋乳痕 (175 - 立) 直蓋乳痕 (175 - 175
3	1350-1150	200	: 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4	300-100	200	អ2្ម∑75 ៩ មិ≗្រ
5	30-0	30	<u> </u>
			그는 그는 그는 그를 가입을 됐다. 통기를 회회하는 그는
Cleaned locati	ion, fenced pit, and i	netalled a	ry note marker. When pit is dry
			r and reseeded to BLM Specification
TOCACTON WILL	be restored to origin	iai consoni	The special contractor
		f ear	
		Bar-	
Subsurface Safety Valve: Manu. and Type		Set @ Ft.	
18. I hereby certify that t	he foregoing is true and correct	No. of the second	
SIGNED 210 28 Miles	susett TITLE Drlg	.&Prod.Foi	reman DATE May 1, 1980
H. D. HOLLIX	SWORTH		
	SWORTH	ederal or State of	

*See Instructions on Reverse Side

U. S. GEOLDONGAL SURVEY FARMINGTON, N. M.

_ TITLE _