

N

30-043-20517

12-3-80

F. Loc. 820/S;1620/E Elev. 6732 GL Spd. _____ Comp. _____ TD _____ PB _____Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
Csg.Perf. _____ Prod. Stim. _____T
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ Grav. _____ Ist Del. _____ s _____

TOPS		NITD	X	Well Log	TEST DATA						
Kirtland		C-103		Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104		Electric Log							
Pictured Cliffs				C-122							
Cliff House		Ditr		Dfa							
Menefee		Datr		Dac							
Point Lookout											
Mancos											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											
		160									

P

o

EXT

i Rusty Chacra SA s 27 T 22N R 7W U 00per. Dome Petroleum Corp. Dome Navajo 27-22-7 No. 3

Dome Navajo 27-22-7 #3

0-27-22N-7W

Dome Petroleum Corp.

June 3, 1982

Dome Petroleum Corporation
3600 Southside River Road
Farmington, New Mexico 87401

Gentleman:

Reference is made to your Applications for Permit to Drill (APDs) for the following wells:

No. 1 Dome Navajo 27-22-7, NW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 27, T. 22 N., R. 7 W., Sandoval County, New Mexico, lease N00-C-14-20-5364

No. 2 Dome Navajo 22-22-7, NE $\frac{1}{4}$ NW $\frac{1}{4}$ sec. 22, T. 22 N., R. 7 W., Sandoval County, New Mexico, lease N00-C-14-20-5356

No. 3 Dome Navajo 27-22-7, SW $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 27, T. 22 N., R. 7 W., Sandoval County, New Mexico, lease N00-C-14-20-5363

The subject APDs are hereby rescinded and returned due to drilling operations not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred of the referenced drill sites.

Sincerely yours,

Elliott
For James P. Sims
District Oil & Gas Supervisor

Enclosures

cc: SCR, MS 410
BIA, Window Rock
NMOCC

