5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR	NM 25611-
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	6 7 C 2 C 2 C 2 C 2 C 2 C 2 C 2 C 2 C 2 C
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	9 54DM 00 15405 MARS
	8. FARM OR LEASE NAME
1. oil gas other	Ceja Pelon 9. WELL NO.
2. NAME OF OPERATOR	3. WELLING.
Lewis Energy Corporation, c/o K&A/Helton	10. FIELD OR WILDCAT NAME?
3. ADDRESS OF OPERATOR	Wildcat Island
2200 Security Life Bldg., Denver, CO. 80202	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Section 35-T21N-R4W NMPM
AT SURFACE: 990' FSL, 980' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Sandoval New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15 ELEVATIONS (SHOW DE VOR AND MO)
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6,968' GR, 6,978' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0,900 GR, 0,970 RB-1
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	
ABANDON*	
(other) Progress Report	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all pertinent details and give pertinent dates
including estimated date of starting any proposed work. If well is di- measured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinent	t to this work.)*
MI&RUCT Jan. 17, 1981. Drilled 6 1/4" hold	e to 4 798 to 1 be 3 factor
Ran 622', 4 1/2" OD, 10.5 lb., J-55, STC New Casing set as liner from	
4,782 to 4,150' cemented in place with 70 sx 50/50 POZ 25 Gel with Tiwt	
pack-off type liner hanger. Reversed out 14 sx. မြန်မျိုး မြို့မြို့မြို့မြို့မြို့မြို့မြို့မြို့	
Perforated interval 4,618-28, 4,644-54, 4,	665-75 w/1 jspije eb to 23,7 ij 981.
Testing.	Self self self self self self self self s
	ridue not t Las spiration and more spirate of a spiration and spirate of a enotion as a low a more and low a more long and
	e to
	म श्री भ की भ की भ की भ की भ की भ की भ की भ क
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct Asst. Oper. 1	Mar. 호텔 이 발로 기계
SIGNED TITLE K&A/Helton	DATEMarch 6. 1981
(This space for Federal or State office	
tins space for receial or State onic	ce use) and the control of the contr
APPROVED BY TITLE TOTALL FOR THE CONDITIONS OF APPROVAL, IF ANY:	DATE <u>デンタウン ガー ボラル :</u>
MINIOUS NATIONAL II ANII NO MINIOUS NATIONAL II ANII NATIONALI NATIO	
Nivious Commence of the Commen	
	ត្រូវ <u>ដ្ឋា</u> ន ឲ្យូស៊ូ

*See Instructions on Reverse Side

MAR 1 1 1987

FARMINGTON DISTRICT