

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
RUTH ROSS
3. ADDRESS OF OPERATOR Santa Fe NM 87501
P. O. BOX 464 Santa Fe
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
1240' ENL 1135' ENL
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:


- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐

(other) Notice of reaching total depth.

5. LEASE
NM 12805
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
9. WELL NO.
1 Cuba
10. FIELD OR WILDCAT NAME
C
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SW 1/4 Sec. 5 T20N R1W
12. COUNTY OR PARISH
Sandoval
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3927' GP



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We spudded on December 31, 1980, and reached TD of 305' on January 9, 1981.

Set 8 5/8 inch π surface casing at 110'

Testing



Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED James E. Chace TITLE Agent DATE January 28, 1981

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE

FEB 10 1981

FARMINGTON DISTRICT

*See Instructions on Reverse Side

NMOCC