UNITED STATES	5. LEASE ( \$ \) \$ \) \$ \) \$ \) \$ \) \$ \) \$ \) \$
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME ఓఓక్ స్ట్రామ్
	7. UNIT AGREEMENT NAME.
SUNDRY NOTICES AND REPORTS ON WELLS	Addition a sign
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME & SAR
1 sil gas —	San Isidro 🖫 🕺 ១៦ 🗒
1. oil gas other	9. WELL NO. 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. NAME OF OPERATOR	
Lewis Energy Corporation, c/o K&A/Helton	10. FIELD OR WILDCAT NAME Wildcat North
3. ADDRESS OF OPERATOR 2200 Security Life Building, Denver, CO 80202	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA A STOOM POW AMPIN
below.)	Section 15-T20N-R3W, NMPM
AT SURFACE: 660' FNL, 990' FNL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Sandoval New Mexico
AT TOTAL DEPTH:	14. API NO. 3.5.5.1
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6,855 GL-
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  (NOTE: Report results of multiple completion or zone change on Form 9-330)	
CHANGE ZONES	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
(other) Spud and Surface Casing	- SECONE COM
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,	
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
measured and true vertical depths for all markers and zones pertine	
그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
Spudded 14 3/4" hole at 2:30 p.m. on <u>January 21</u> , 1981.	
Drilled to 228'. Ran 208' of 9 5/8", 36#, K-55, LTC, (new)	
casing and set at 223' with 200 sx, Class B cement with 2% CaCl <sub>2</sub> . Cement	
circulated. Plug down at 11:15 p.m. on January 22, 1981 ুর্নীয়ের	
a to Code Value Many and Type	<u> </u>
Subsurface Safety Valve: Manu. and Type	일반 등 기계 등 기
18. I hereby certify that the foregoing is true and correct K&A/He]t	
SIGNED SIGNED TITLE Asst. Mrg., Oper. DATE February 5, 1981	
(This space for Federal or State o	ffice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	
	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
NMOCC	원회교환 · 환경 1 원생활

NMOCC
•See Instructions on Reverse Side

... Bh/