

N

30-043-20534

1-7-81

F. Loc. 840/N;1780/W Elev. 6756 GL Spd. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. _____ s.														
I.P. _____		TOPS		NITD	X	Well Log	TEST DATA						Ref.No.	
				C-103		Plat	X	Schd.	PC	Q	PW	PD		D
Kirtland				C-104		Electric Log								
Fruitland						C-122								
Pictured Cliffs														
Cliff House				Ditr		Dfa								
Menefee				Datr		Dac								
Point Lookout				40										
Mancos														
Gallup														
Sanostee														
Greenhorn														
Dakota														
Morrison														
Entrada														

P
o
o

Undes Gallup Co. SA S 27 T 22N R 7W U C Oper. Dome Pet. Corp.

Les. Dome Tesoro 27 No. 2

Dome Tesoro 27 #2

C-27-22N-7W

Dome Pet. Corp.



July 13, 1982

Dome Petroleum Corporation
3600 Southside River Road
Farmington, New Mexico 87401

Gentlemen:

Reference is made to your Application for Permit to Drill (APD) well No. 2 Dome Tesoro 27, NE¹/₄ sec. 27, T. 22 N., R. 7 W., Sandoval County, New Mexico, lease NOO-C-14-20-5365. The subject APD is hereby rescinded and returned due to drilling operations not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site.

Sincerely yours,

Sue E. Umshler
for James F. Sims
District Oil and Gas Supervisor

Enclosure

cc: SCR, MS-410
BIA, Window Rock
NMOCC