

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR
DOME PETROLEUM CORP.

3. ADDRESS OF OPERATOR

3600 Southside River Rd., Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 475' FNL, 930' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON *

(other) Extension of APD

RECEIVED


JAN 14 1992

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Dome Petroleum Corp. requests an extension of the Application For Permit To Drill on the above well for 6 months.



Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED H. D. Holdingsworth TITLE Area Prod. Supt. DATE January 8, 1982

H. D. Hollingsworth

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Extended to 8-5-82

***See Instructions on Reverse Side**

NMOCC

APPROVED
AS AMENDED

JAN 12 1982

For JAMES F. SIMS
DISTRICT ENGINEER