DEPARTM		JNITED STATES SUBMIT IN TRIPLICATES (Other instructions on re (Other instructions on re verse side)  EOLOGICAL SURVEY			AND SERIAL NO.
		CES AND REPORTS		6. IF INDIAN, ALLOTTER	OR TRIBE NAME
OIL XX GA	AS OTHER	7. UNIT AGREEMENT NA N/A	M IS		
2. NAME OF OPERA	TOR	8. FARM OR LEASE NAME			
RIJAN O	IL COMPANY,	Rijan Oil	Company, Inc		
3. ADDRESS OF OPE	RATOR	9. WELL NO.			
20 First	t Plaza, Su	Federal 2-27 10. FIELD AND POOL, OR WILDCAT Wildcat			
	LL (Report location cl				
2310' FSL & 990' FWL			auciec 1387	11. SEC., T., B., M., OR BLK. AND SUBVEY OR AREA	
		į	COCHORNE GURVEY	Sec. 27, T	19N,R3W,NMP
14. PERMIT NO.		1 15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
		6782' GR	- Afternoon	Sandoval	New Mexico
16.	Check Ap	propriate Box To Indicate I	Nature of Notice, Report, or	Other Data	
	NOTICE OF INTEN	UENT REPORT OF:			
TEST WATER S	AT .	CLL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING V	ARING
SHOOT OR ACID	IZE	BANDON*	SHOOTING OR ACIDIZING	ABANDONME	NT -


(Other) Resume Amilling operations X
(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)\*

> Moved on Four Corners Drilling Company rig No. 2. Started drilling cement 04:30 a.m. August 25, 1981 Tested casing with 625 psi for 15 minutes. Held ok. Now drilling 7 7/8% hole to a proposed total depth of 5200%,

CHANGE PLANS

REPAIR WELL

(Other)



18. I hereby certify that the foregoing is true and correct				
SIGNED (ANEW) (Ruen)	TITLE	Petroleum Engineer	DATE	8/25/81
(This space for Federal or State office use)				4.1
APPROVED BY	TITLE		DATE	

\*See Instructions on Reverse Side

NMOCC

SAMMON.