

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-330-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR

Northwest Exploration Company

3. ADDRESS OF OPERATOR

P.O. Box 90, Farmington, N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 850 FNL & 1850 FWL

AT TOP PROD. INTERVAL: 850 FNL & 1850 FWL

AT TOTAL DEPTH: 850 FNL & 1850 FWL

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☒  
☒  
☐  
☐  
☐  
☐  
☐  
☐

7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Natani

9. WELL NO.  
#17

10. FIELD OR WILDCAT NAME

Undesignated Rusty Chacra

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 3, T21N, R6W

12. COUNTY OR PARISH

Sandoval

13. STATE

N.M.

14. API NO.

30-043-20610

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6938' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

AUG 24 1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8-14-82 MOL & RU. PU 3-7/8" bit on 2-3/8" tbg & cleaned out 1860'. Tested csg to 3000# - OK. Circ hole w/ 2% KCl & spotted 250 gal 7-1/2% HCl Blue Jet ran GR/CCl and perf'd 18 holes from 1600' to 1707'. Western frac'd w/ 5000 gal pad followed w/ 75,000# 20/40 sand at 1-2 ppg. (All wtr 2# FR/1000 gal & 2% KCl). (Total fluid 1616 bbls). MIR 47 BPM, AIR 47 BPM, MIP 2600#, AIP 2000#. Job done at 1515 hrs 8-14-82. ISIP 600#. Ran 52 jts 2-3/8", 4.7#, J-55 EUE & landed at 1636'. Gauged well at 0 MCF/D. SI at 2000 hrs 8-14-82.

8-15-82 Rig released at 0600 hrs. SI after frac

NOW WAITING ON IP TEST.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE August 20, 1982

Donna J. Brace

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY.

ACCEPTED FOR RECORD

B  
djb/3

\*See Instructions on Reverse Side

~~NA~~ NMOC C